

BUILDING SAFETY CERTIFICATENo. R2B/C.C/665Dated 29-04-2026

It is certified that the existing building of CARMEL SCHOOL CHARTROO, CHANDAK
at Chandak, Poonch (M) Tehsil Javeli, JPK

185/01

(address) is having block(s)/Floor(s) as per details below.

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	4	—	—	—	—

The building is owned/occupied by School authorities of CARMEL SCHOOL CHARTROO
have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (R&B) Division Poonch
on 28-4-2026 in the presence
of School authorities, Manager, Sr. Manju P.A. Carmel School Chandroo, Chandak
and that the building/premises is fit for occupancy for running school with effect from 2026-26 for a period of one years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The building structure shall remain safe and sound as per NBCs 16
2. Any structural modifications or additions shall be done only with prior approval
3. The building shall not be used for any purpose other than running the school without prior approval
4. Proper ventilation and lighting must be maintained in all classrooms as per JPK SER, 2010

Issued on 29/4/2026 at Poonch by

Signature with Seal:


Executive Engineer
PWD (R&B) Division
Poonch

Name: ER S. K. S. K. S.Designation: Executive EngineerName & Address of Department/ Office: Poonch